

SERVICE BULLETIN

Spring Pad Replacement Part #'s 16-861-40, -41, -42, -43

Date: 3/11/2008

Models affected: B0-210-36, B0-210-36AMB, B0-248-36, B0-248-48, B0-254-36, B0-254-48, B0-T48-48, BT-248-36, BT-248-48, BT-280-36, BT-280-48, ET-030-48, RE-380-36, RE-380-48

AFFECTED TRUCKS: All manufactured before 3/1/2008.

SERVICE PROCEDURE:

The spring pads listed were modified in February, 2008.

Depending on the age of the vehicle, additional components may be required when replacing the spring pads. The new design offsets the park brake cable to better align with the attachment point on the brake assembly. Older vehicles may require the installation of the 41-350-59 extension lever. If the vehicle is already equipped with the 41-350-59 Extension Lever, then no other parts are required.

PARTS REQUIRED		
Part number	Description	QTY
41-350-59	EXTENSION, PARK BRAKE LEVER	2
88-081-11	BOLT, EXTENSION LEVER	4
88-089-81	NUT, EXTENSION LEVER	4

WARRANTY INFORMATION: No warranty allowance.

